

FIG. 1

$W_k^n$	N=4	N=8	N=16	N=32	N=64	N=128
k	0	0	16	32	64	128
					0	0
					64	64
				32	32	32
					96	96
				16	16	16
					80	80
				48	48	48
					112	112
				8	8	8
					72	72
					40	40
					104	104
				24	24	24
					88	88
					56	56
					120	120
				4	4	4
					68	68
					36	36
					100	100
				20	20	20
					84	84
					52	52
					116	116
				12	12	12
					76	76
					44	44
					108	108
				12	28	28
					92	92
					60	60
					124	124

$W_k^n$	N=4	N=8	N=16	N=32	N=64	N=128
k	2	2	10	18	50	114
				10	10	10
					74	74
				26	42	42
					106	106
				26	26	26
					90	90
				6	58	58
					122	122
				6	6	6
					70	70
					38	38
					102	102
				22	22	22
					86	86
					54	54
					118	118
				14	14	14
					78	78
					46	46
					110	110
				30	30	30
					94	94
				30	62	62
					126	126

$W_k^n$	N=4	N=8	N=16	N=32	N=64	N=128
k	1	1	9	17	33	97
				17	17	17
					81	81
				9	49	49
					113	113
				25	9	9
					73	73
					41	41
					105	105
				5	25	25
					88	88
				5	57	57
					121	121
				13	5	5
					69	69
					37	37
					101	101
				21	21	21
					85	85
				29	53	53
					117	117
				13	13	13
					77	77
					45	45
					109	109
				29	29	29
					93	93
				61	61	61
					125	125

$W_k^n$	N=4	N=8	N=16	N=32	N=64	N=128
k	3	3	19	51	115	231
				11	11	11
					75	75
				27	43	43
					107	107
				27	27	27
					91	91
				59	59	59
					123	123
				7	7	7
					71	71
					39	39
					103	103
				23	23	23
					87	87
				15	55	55
					119	119
				31	15	15
					79	79
				31	47	47
					111	111
				63	31	31
					96	96
				63	63	63
					127	127

FIG. 2





FIG. 3



**FIG. 4**